

2017 USRA B-MOD RULES

<http://www.usraracing.com/rules/>

RULE ADDITIONS:

OIL PANS - MUST HAVE 1 INCH INSPECTION HOLE ABOVE OIL LEVEL FOR INSPECTION. Inspection hole needs to be installed in a manner were tech official can see crankshaft & rods for proper inspection. **IF NO INSPECTION HOLE IT WILL BE ASSUMED YOU ARE CHEATING AND YOU WILL BE DISQUALIFIED!!!**